

DETAILS OF CONTRACTS AWARDED ON NOMINATION BASIS

PERIOD :OCT., 2022.							
Sl.No.	Name of the Project	Details of Work	Name of the Awardee	Type or Nature of Tenders (Single / Nomination etc.)	Brief Reason for Single Tender / Nomination etc.	Work Order No./Supply Order No. and Date	Value of Contract Awarded
1	CTPS	Testing of Conveyor Belt Samples at IRMRA, Thane through Third Party Govt. Lab.	The Indian Rubber Manufacturers Research Association (IRMRA) Plot no. 254/1B, Road No. 16V, Wagle Industrial Estate, Thane (W)-400604, Thane, Pincode: 400604	Single (Urgency)	User section has mentioned that condition of belt is very poor. Some of the conveyor belts are running since commissioning and not in reliable condition. Sudden damage of these conveyor belts will hamper coal curshing and feeding of coal to bunker and will ultimately cause generation loss and demurrage in rake unloading. Keeping in view of the urgency expressed by user section and considering the time for testing of belts, it is felt prudent to send the conveyor belt samples to IRMRA, Thane.	DVC/Contract/CTPS/FIELD QUALITY ASSURANCE/C&M/Works and Service/00010 Dated 27/10/2022	Rs.103400.00

2	CTPS	Contract for removal and fitting of transmission assembly and torque converter of dozer BD-155 & transmission assembly of BD-355 of MT shop, CTPS.	A.K.ENTERPRISES SHOP NO. 13 ,NEAR EMPLOYMENT EXCHANGE, DHANBAD, Pincode: 826001	Single (Urgency)	Out of two available departmental dozers one of Model BD-355 was in breakdown condition, due to failure of its transmission system . To overcome the problem transmission pump of the same was replaced, but the issue was not resolved. On further investigation it was found that transmission assembly of the same is to be replaced. Further, on dated 20.09.2022 another departmental Dozer model BD 155 got breakdown, because of failure of transmission system as well as problem in its torque converter. After breakdown of both departmental dozers, only single hired dozer is available to carry out all the essential activities of CHP. Further It is not possible to meet the coal requirement of both the units with the help of only single hired dozer, which leads to generation loss. To sustain the generation, it is required to make both the dozers available within shortest possible time. To overcome the current crisis and to avoid generation loss it is prudent to engage an outside agency with proven credential to attend the job on urgency basis.	DVC/Contract/CTPS/ MT SHOP/C&M/Works and Service/00041 Dated 21/10/2022	Rs.112200.00
---	------	--	---	---------------------	--	---	--------------